

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020806**Date Inspected:** 29-Oct-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yan Hua**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment Assembly**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Ramesh Gade, was present during the times noted above for observations relative to the work being performed.

Bay 16/ Steel Barriers

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 2F position of W5-SB25-001 Steel Barrier internals weld # W5-SB25-001-126. The welder is identified as 066751. ZPMC Quality Control (QC) is identified as Guo Pin. The welding variables recorded by QC appeared to comply with WPS-B-T-2132. See attached photograph Pic_001.

Bay 16/ Steel Barriers

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 2F position of W5-SB1-044 Steel Barrier internals weld # W5-SB1-044-130. The welder is identified as 068858. ZPMC Quality Control (QC) is identified as Guo Pin. The welding variables recorded by QC appeared to comply with WPS-B-T-2132.

Bay 16/ Steel Barriers

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 3F position of W5-SB1-050 Steel Barrier internals weld # W5-SB1-050-055. The welder is identified as 201074. ZPMC Quality Control (QC) is identified as Guo Pin. The welding variables recorded by QC appeared to comply with WPS-B-T-2133.

OBG Segment 12AW

This QA Inspector observed the following work in progress:

During in process inspection this QA Inspector observed ZPMC NDT personnel performing Magnetic Particle Testing (MT) on Cross Beam side Corner Assembly SP to PP110 West welds. See attached photograph Pic_002.

Bay 14 / OBG Segment 1 East

This QA Inspector observed the following work in progress:

Shielded Metal Arc Welding (SMAW) in the 3F position of SEG3011E-035 located on PCMK SEG 3011E. The welder is identified as 066416. ZPMC Quality Control (QC) is identified as Guo Xing Hui. The welding variables recorded by QC appeared to comply with WPS-B-P-2113-FCM-1.



Summary of Conversations:

No relevant conversations reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (+86)15000 42 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Gade,Ramesh	Quality Assurance Inspector
Reviewed By:	McClendon,Timothy	QA Reviewer
